

Safety Bulletin 10 of 2016

EPIRB Recall

Orolia Group Limited, owners of Kannad Marine have become aware of an issue affecting Kannad SAFELINK EPIRBs which could result in the beacon not operating in an emergency situation.



Part No's Affected. Description. Date Range.
K1202311. EPIRB SAFELINK Manual+ GPS. All.
K1202367. EPIRB SAFELINK Auto GPS. All.

If you suspect that you may have an affected beacon (only Safelink EPIRB auto and manual), you should not use the SAFELINK as the primary Search and Rescue beacon on board your vessel.

Visit www.safelinkepirbsupport.co.uk for full details and instructions for return and replacement.