



**Notice to Mariners № 01 of 2018**

**Jersey South Coast – BA Charts 2669 and 3656**

**Wave recorder buoy, South Coast of Jersey**

1. Mariners are advised that the Wave recorder buoy in position 49° 05'.00N 002° 13'.00W is missing.



Captain Bill Sadler  
Harbour Master, Jersey Harbours

19/01/18